
SWM CNC Teacher Training Session

Session 201/202: Making a wooden mallet customized with initials using the Vectric Inlay Toolpath (Standard Inlay)

This session is about spicing up your projects by adding an inlay using the Inlay Toolpath function in Vectric software. To be able to complete this project during the time allotted for this training session, premade blanks were cut of the mallet head and handle in ¾" Baltic Birch using the Pocket and Profile toolpaths. In addition, a piece of Cherry was milled to fit a pocket that was cut in the premade blanks. This Cherry will be used to make the male inlay pieces.


Once it is cutting time please pick up one of the ¾" Birch blanks and one of the 2"x3.5"x0.25" pieces of Cherry. The Birch Ply blank should look like this.



TJI

The Vectric INLAY TOOL PATH is a very powerful and easy way to automatically modify your geometry so that the male inlay parts fit perfectly into the female pockets every time. Remember that unlike VCarve inlays, standard inlays are dependent on tool diameter. While the INLAY POCKET tool path looks very similar to a regular pocket toolpath and the INLAY INSERT toolpath looks very similar to the profile toolpath, there is one HUGE difference. Using the "Create Inlay Toolpath" function eliminates the need to modify your vectors to accommodate your tool diameter as this gets done automatically. In this session I'll explain this in greater detail.

Here is what happens when using the regular pocket and profile toolpaths to make a standard inlay vs. using the auto inlay toolpath functionality...



Let's get started. Part one is designing your project. In this case we have started the project design for you.


- 1) Load the supplied file and verify the JOB SETUP parameters as:
 - a. Double Sided
 - b. 14W x 5H x 0.710 Thick
 - c. Material Surface
 - d. Lower Left Corner
 - e. Flip bottom to top
 - f. Std Resolution

Once you have the file open you should see this image to the right.

You are looking at the top side showing a rectangular vector that was used to create a pocket where the Cherry wood will be secured prior to cutting. We will be putting text vectors in this area to cut the male inlays. Also you can see light colored vectors from the other side of this project.

11 - Head -






While viewing this side, one of the Mallet Head vectors needs to be copied to the other side.


That layer is currently locked so first it needs to be unlocked.

- 2) Go to Layers
 - a. Select Head layer
 - b. Head layer is now active as show by the highlighted layer name and Head is shown at the top layer menu.
 - c. Head Layer is locked as noted by the lock symbol over the lightbulbi. Right click on head and choose unlock from the drop down menu

2D View 3D View

- d. While the Head layer is active and unlocked, select the right mallet head vector
- e. Right click on the right mallet head vector and select Copy to Other Side from the drop down menu (Shown on right).
- f. Change view to Top Side to see that the head vector transferred properly.





- 3) Create a Layer for the text (your initials) and add the head vector to that layer.
 - a. Select the Head vector
 - b. Right click and choose Move to Layer on drop down menu
 - c. Choose New Layer and enter Letters
 - i. Check box New Layer is Visible
 - ii. Check box New Layer is Active
 - iii. Click OK
 - d. Note Letters is currently the layer you are working on. 2D View 3D View M the Letters
 - e. Select the Head vector
 - f. Right click, choose Move to Layer and pick Letters
 - g. Relock the head layer the same as it was unlocked
- 4) Use "DRAW TEXT" and enter your 3 initials for the inlay
 - a. True Type Font
 - b. Select Ariel font
 - c. Select Bold

d.

- d. Select Center Alignment
- e. Text Height 1.125" (some text combinations will allow 1.25")
- f. Close the text box
- 5) Center your text inside the mallet head vector.
 - a. Click on the text your just created
 - b. Hold down the shift key
 - c. Click on the Mallet head vector



to center your text inside the mallet head.

Laver Name

Drawing Color

New Layer is Visible 🛛

New Layer is Active

Letters

Cancel


- 6) Adjust spacing as needed using the "Edit text spacing and curve" icon.
 - a. Place cursor between letters and click to move them closer together.
 - b. Place cursor between letters, hold down shift and click to move them further apart.
- 7) Create a copy of the text and align it the same way to the rectangle in the lower right hand corner.
 - a. Click on the text you just created
 - b. Hold down the control key and press "C"
 - c. Hold down the control key and press "V"
 - d. Click on the text
 - e. Hold down the shift key
 - f. Click on the lower right rectangle vector




Select 📐

g.

- h. Your file should look like this with your initials instead of TJI.
- 8) DONE, ready to make TOOL PATHS







Crea	te Ve	ctors		
\odot	٢		\odot	☆
X	3	5	ď	
Т	T		T	ABC
1	₽?₽			

Part two is creating toolpaths for both the letters and the pockets.

VERY IMPORTANT you MUST use the exact same tool diameter for BOTH toolpaths.

- Review Material Setup 1)
 - a. Tool clearance to 1" or less if comfortable with less

W 🗷 🗅 🗙 🗃

鲁鲁鲁 🏠 🎍 🗿 🕅 🔂 🛱

- INLAY Tool Path (always cut letters first) 2)
 - a. Select text
 - b. Open Inlay Toolpath menu
 - c. Select Male Inlay (Straight)
 - d. Set cut depth to 0.26"
 - e. Select tool 0.125" End Mill
 - i. 50 inches/min
 - ii. Pass depth 0.125"
 - iii. Speed 16,000 RPM
 - f. Climb
 - g. Offset Allowance 0.01"
 - h. No tabs needed as CA glue will hold letters in place
 - i. Add Ramps to toolpath
 - i. Smooth
 - ii. Distance 0.25 (2XD min)
 - Change name to "InlayM"
 - k. Calculate

j.

- ١. Preview toolpath to make sure everything looks good
- 3) INLAY Tool Path (cut pockets second, this allows running a revised toolpath if the letters don't fit before your remove your work piece)
 - a. Select text
 - b. Open Inlay Toolpath menu
 - c. Select Female Inlay (Pocket)
 - i. Set cut depth to 0.25"
 - ii. Select tool 0.125 End Mill
 - 1. 50 inches/min
 - 2. Pass depth 0.125"
 - 3. Speed 16,000 RPM
 - iii. Offset/Climb
 - iv. Ramp plunge Distance 0.25"
 - v. Change Name to "InlayF"
 - vi. Calculate
 - d. Preview toolpath to make sure everything looks good
- Save above Tool Paths to USB drive 4)
 - a. Select the correct post processor for your CNC machine from the drop down menu
 - b. Add tool description to file name if desired
 - Save GCode file c.
 - d. Save ENTIRE project file
- 5) DONE - ready to cut

loolpaths	_	Ľ	9? 4	
🌾 Material Setup	,			
Active sheet:	Mallet	Master		
Thicknes	s 0.70	02 in	ches	
XY Datum) []Us			
<i>_</i> ○		0.0		
Show detailed summar		0.0		
-	y on cool	baen tab	_	
Side Z-Zero (Top)	aterial Sur	face		
	achine Ber			
			=	
Model Position in Mate			.	
		bove Mod inch		
-		elow Mode		
	0.70	12 inch	es	
Model Thickness 0.		Set.		
Modeling Plane Z 0.	0 inches	-		
		202		
Rapid Z Gaps above				١
Izz Z1 Clearance	_		ches	I
Plunge (Z2	2) 0.	2 in	ches	I
Home / Start Positio	on			/
X: 0.0	Y: 0.	.0	/	
Z Gap above Mat	erial 3.	.0		
	-		1	
OK	(Cancel		
	~			
Tanala lab				
Female Inla	ay - FO	скег		
Cutting Depths	0.00		14.5	
Start Depth		0.0	ind	
Cut Depth (C)	0.25	inc	che
Tools:				
-	(h)			1
	ICH1			
End Mill (0. 125 in				
End Mill (0. 125 in)				Ľ

Select


O Offset

Raster Angle

Profile Pass

Vector Selection: Manual

Name: InlayF Calculate



Selector ...

Close

Male Inlay - Insert

Start Depth (D) 0.0

Select ...

Direction O Climb O Conventional

Length 0.5 inches

Thickness 0.125 inches

Smooth Zig Zag

O Spiral

Allowance offset 0.0

Do Separate Last Pass Allowance (A) 0.0

Reverse direction

Add tabs to toolpath

3D tabs

 \bigcirc

Specify Ramp ...

Ramp Leads Order Start At Add ramps to toolpath

Ramp on Lead In ODistance 0.3 inches

Angle 20.0 degrees

Cut Depth (C) 0.26

Tool: End Mill (0.125 inch)

inches

inches

Edit .

inche

Edit Tabs

Selector ..

Close

Edit Passes

(10)

Cutting Depths

Passes: 2

Machine Vectors...